QUALITY CONTROL

Name of the Work:	Constructtion of RCC drain in 2nd main BHEL mini colony from Pipeline road in BHEL mini colony fro, pipeline road in W.No.13
Job No:	013-12-000065
Work order No:	39/13-14 D: 10-7-2013
BR No:	528/30.11.2013

On verification of quality control test reports available in the file and also from inspection report of Technical Team Deployed for this purpose generally the work executed is satisfactory. Compliance of Quality Control Test Reports as per MORT&H at this stage is not feasible since this work was executed 1½ years back.

Assistant Executive Engineer
Shetty Halli Sub Division
Bruhat Bengaluru Mahanagara Palike

Executive Engineer
Dasarahalli Division, Dasarahalli Zone
Bruhat Bengaluru Mahanagara Palike